

INSTRUCTION



S1x3	S2x23	S3x20	S4x4	S5x16	S6x16	S7x12
				title &		
	4x30mm	6x30mm	6x25mm	alle		
S8x4		S9x21	S10x2	S11x2	S12x2	S13x1
E CB° CG° · CG · S	a a a a		\bigcirc			
b)	3.5x14mm				
S14x2						


 \bigcirc


PARTS					
ITEM	QTY	ITEM	QTY	ITEM	QTY
a	1	g	1	L2	1
b	1	h	1	k	2
С	1	i	1	m	2
d	2	J1	1	n	2
е	2	J2	1	p1	2
f	2	L1	1	p2	2





S5x8	S6x8	\$7x8
util b	æ	


1




















				4			
S5x8	S6x8	S7x4	S2x8	S8x4	S9x8	S10x2	S11x2
title a	æ		- 4x30mm	b b		\bigcirc	








5 S14x2 S8x4 S1x1 S9x13 S12x2 S13x1 S2x1 6 Ć - \bigcirc a a a 0 4x30mm S4 · E2· F **G**: 3 a a b **S**13 S2 \odot S14′ S'1 Wall S9 S9 a S12 -0 S99 S9

S1x2	S2x2	
	4x30mm	



6