



ASSEMBLY INSTRUCTION






# DEERFIELD COFFEE TABLE




**ROWICO**

HOME



<p>1 x 1</p> 	<p>A x 8</p>  <p>M6 x 16</p>
<p>2 x 1</p> 	<p>B x 8</p>  <p>Ø6/Ø16</p> <p>C x 1</p>  <p>N4</p>



Note:  
 Improper use, improper  
 assembly and mishandling  
 may lead to defects/ cracks  
 appearing.

